



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

January 29, 2007

Jim Runquist
Temple Mountain Energy Asphalt Ridge LLC
4526 Ridgeview Drive
Eagan, Minnesota 55123

Subject: Operations Map, TME Asphalt Ridge, Cameron #1 Mine, S0470036, Task 1621, Uintah County, Utah

Dear Mr. Runquist:

On December 14, 2006, and January 22, 2007, the Division received operations maps for the Cameron #1 Mine in response to cessation order MC2006-03-14-01. The map received January 22, 2007, with a scale of 1"=180' appears to be the most accurate and shows three areas that have been reclaimed, but it does not show the operations area, the mining area, and the overburden and topsoil piles. The two maps received December 14, 2006, show the various operations areas, but they conflict with the January 22, 2007, map, and they do not have scales.

Please submit a map at a scale of about 1"=200' showing the different operations areas. The Division suggests showing these operations areas on the map submitted January 22, 2007.


From our discussions, it appears most of the reclamation work to abate the cessation order has been completed, but top soiling and seeding have been delayed because of the very cold weather and frozen ground. It has become apparent, however, that a revised map is not needed *before* completing the reclamation.

Enclosed with this letter is a modification to the cessation order allowing until February 26, 2007, to complete the reclamation work and to submit a revised map. Please make every effort to finish the map and reclamation work by this date.

Jim Runquist
Page 2 of 2
S0470036
January 29, 2007

We appreciate your cooperation. If you have questions about this letter or about the requirements for the operations map, please call Paul Baker at 801-538-5261.

Sincerely,

A handwritten signature in black ink that reads "Daron R. Haddock". The signature is fluid and cursive, with the first name "Daron" being more prominent than the last name "Haddock".

Daron R. Haddock
Permit Supervisor
Minerals Regulatory Program

DRH:PBB:pb
P:\GROUPS\MINERALS\WP\M047-Uintah\S0470036-Cameron\Final\def-map-01252007.doc



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Page 1 of 2

MODIFICATION of
Cessation Order MC2006-03-14-01

To the following Permittee or Operator:

Name: TME Asphalt Ridge

Mailing Address: 4526 Ridgeview Drive, Eagan, Minnesota 55123

Mine Name: Cameron #1

Permit Number: S0470036

Utah Mined Land Reclamation Act, Section 40-8-1 et. seq., *Utah Code Annotated (1953)*:

Notice of Violation No. _____ dated _____, 20 ____

Cessation Order No. MC2006-03-14-01 dated November 15, 20 06

Part 1 of 1 is modified as follows: By February 26, 2007, the operator must submit an operations map showing show topsoil and overburden stockpiles, roads that will be used as part of the mining operation, equipment locations, and areas from which mineral materials will be extracted from the earth. Reclamation of areas in excess of the five-acre operations area must be completed by this same date.

Reason for modification is: The operator needs additional time to complete reclamation because of weather conditions. Additional time for completing the map is to allow corrections on previously-submitted maps.

Date of service/mailing: _____

Time of service/mailing _____ ☐ a.m. ☐ p.m.

Date of inspection: November 1, 2006

Jim Runquist

Permittee or Operator Representative

President

Title

Signature

Paul B. Baker

Division of Oil, Gas & Mining Representative

Reclamation Biologist

Title

Signature

O:\M047-Uintah\S0470036-Cameron\non-compliance\mod2-mc2006031401.doc